

INTERTEK TESTING SERVICES

Report No.: HK09040269-1
Model No.: 24351(1013024/6012543)
Sample No.: 2/2


Pursuant to FCC Part 15 Section 15.225 Emissions Requirement



Ref 0 dBm *Att 30 dB RBW 10 kHz Marker 1 [T1]
*VBW 3 MHz -10.88 dBm
*SWT 100 ms 27.144960000 MHz

1 AP
VIEW

2 AP
VIEW



Tested By: Michael Leung
(Michael Leung)

Date: 15/4/04

Checked By: [Signature]

Date: 16/4/04

Test Result : Pass / Fail / NA