


REV	DETAIL OF CHANGE	DATE	RELEASED BY	AGREED BY
00				



Function Describe :

- 1) Rx unit receive the RF signal and decode it to drive the motor running on different speed.
- 2) Q4, Q2 Twin transistor is for low Battery detect control to made MCU IC be power off.
- 3) There is a over load detect Resistor control for the motor

Client: SPIN Model No. 44210		Spin Master toys Far East LTD.	
Project: ROOM RAIDER			
Drawn by: SHL			
Sheet File Name:	Sheet Title: RX BLOCK DIAGRAM		
Size: A4	Document Number:	Rev.: 00	
Sheet Creation date: 2006-05-20	SHEET 1	OF	1