


INTERTEK TESTING SERVICES

Report No.: HK08091366-1  
 Model No.: 44344  
 Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Ref 0 dBm      Att 30 dB      RBW 3 MHz      Delta 1 [T1 ]  
 \*VBW 3 MHz      -0.08 dB  
 SWT 200 ms      65.600000 ms



Tested By: Michael Leung  
 (Michael Leung)

Date: 3/9/08

Checked By: [Signature]  
 (Frank [Name])


Date: 2/10/08

Test Result : Pass / Fail / **NA**

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Ref 0 dBm Att 30 dB RBW 3 MHz Delta 1 [T1] 0.04 dB  
 \*VBW 3 MHz SWT 80 ms 65.760000 ms



Tested By: Michael Leung  
 (Michael Leung)

Date: 30/9/08

Checked By: [Signature]  
 (Paul Chan)


Date: 2/10/08

Test Result : Pass / Fail / NA

INTERTEK TESTING SERVICES

Report No.: HK08091366-1  
Model No.: 44344  
Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Tested By: *(Signature)*  
(Michael Leung)

Date: 30/9/08

Checked By: *(Signature)*  
(Tony (K...))


Date: 2/10/08

Test Result : Pass / Fail /  NA

INTERTEK TESTING SERVICES

Report No.: HK08091366-1  
Model No.: 44344  
Sample No.: 1/2

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement



Tested By: Michael Lewny  
(Michael Lewny)

Date: 30/9/08

Checked By: [Signature]  
([Signature])

Date: 2/10/08

Test Result : Pass / Fail /  NA