



INTERTEK TESTING SERVICES

Report No.: HK11060687-1
Sample No.: 1/1



Date: 25.JUN.2011 15:10:05



Date: 25.JUN.2011 15:15:43

Bandedge Plot – Pursuant to FCC Part 15 Section 15.249 Requirement