



INTERTEK TESTING SERVICES

Report No.: HK11060677-1
Sample No.: 1/1



Date: 25.JUN.2011 12:23:36



Date: 25.JUN.2011 13:33:51

Bandedge Plot – Pursuant to FCC Part 15 Section 15.249 Requirement