


# INTERTEK TESTING SERVICE

Report No.: 15031419HKG-003

## Equipment Photographs

Model : 44497RX

(Internal)



# INTERTEK TESTING SERVICE



---

Report No.: 15031419HKG-003

## Equipment Photographs

Model : 44497RX

(Internal)



---

# INTERTEK TESTING SERVICE



---

Report No.: 15031419HKG-003

## Equipment Photographs

Model : 44497RX

(Internal)



# INTERTEK TESTING SERVICE



---

Report No.: 15031419HKG-003

## Equipment Photographs

Model : 44497RX

(Internal)



# INTERTEK TESTING SERVICE


---

Report No.: 15031419HKG-003

## Equipment Photographs

Model : 44497RX

(Internal)





# INTERTEK TESTING SERVICE

Report No.: 15031419HKG-003

## Equipment Photographs

Model : 44497RX

(Internal)



# INTERTEK TESTING SERVICE

---

Report No.: 15031419HKG-003

## Equipment Photographs

Model : 44497RX

(Internal)

