
INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)



FCC ID: PQN44578RX2G4
IC: 4438B-44578RX



INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16020340HKG-003(FCC)
16020340HKG-004 (IC)

Equipment Photographs

Model : 44578RX

(Internal)

