


INTERTEK TESTING SERVICE

Report No.: 17060168HKG-003 (FCC)
17060168HKG-004 (IC)

Equipment Photographs

Model : 52116TXH

(Internal)



FCC ID: PQN52116TXH2G4
IC: 4438B-52116TXH



INTERTEK TESTING SERVICE

Report No.: 17060168HKG-003 (FCC)
17060168HKG-004 (IC)

Equipment Photographs

Model : 52116TXH

(Internal)



FCC ID: PQN52116TXH2G4
IC: 4438B-52116TXH


INTERTEK TESTING SERVICE

Report No.: 17060168HKG-003 (FCC)
17060168HKG-004 (IC)

Equipment Photographs

Model : 52116TXH

(Internal)



FCC ID: PQN52116TXH2G4
IC: 4438B-52116TXH



INTERTEK TESTING SERVICE

Report No.: 17060168HKG-003 (FCC)
17060168HKG-004 (IC)

Equipment Photographs

Model : 52116TXH

(Internal)



FCC ID: PQN52116TXH2G4
IC: 4438B-52116TXH



INTERTEK TESTING SERVICE

Report No.: 17060168HKG-003 (FCC)
17060168HKG-004 (IC)

Equipment Photographs

Model : 52116TXH

(Internal)



FCC ID: PQN52116TXH2G4
IC: 4438B-52116TXH


INTERTEK TESTING SERVICE

Report No.: 17060168HKG-003 (FCC)
17060168HKG-004 (IC)

Equipment Photographs

Model : 52116TXH

(Internal)



FCC ID: PQN52116TXH2G4
IC: 4438B-52116TXH


INTERTEK TESTING SERVICE

Report No.: 17060168HKG-003 (FCC)
17060168HKG-004 (IC)

Equipment Photographs

Model : 52116TXH

(Internal)



FCC ID: PQN52116TXH2G4
IC: 4438B-52116TXH

INTERTEK TESTING SERVICE

Report No.: 17060168HKG-003 (FCC)
17060168HKG-004 (IC)

Equipment Photographs

Model : 52116TXH

(Internal)



FCC ID: PQN52116TXH2G4
IC: 4438B-52116TXH



INTERTEK TESTING SERVICE

Report No.: 17060168HKG-003 (FCC)
17060168HKG-004 (IC)

Equipment Photographs

Model : 52116TXH

(Internal)



FCC ID: PQN52116TXH2G4
IC: 4438B-52116TXH