

---

# INTERTEK TESTING SERVICE


---

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)



---

# INTERTEK TESTING SERVICE



---

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)





# INTERTEK TESTING SERVICE

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)



# INTERTEK TESTING SERVICE



---

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)





# INTERTEK TESTING SERVICE

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)



---

# INTERTEK TESTING SERVICE



---

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)



---

# INTERTEK TESTING SERVICE



---

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)



# INTERTEK TESTING SERVICE


---

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)





---

# INTERTEK TESTING SERVICE



---

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)



# INTERTEK TESTING SERVICE



---

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)



---

# INTERTEK TESTING SERVICE



---

Report: 14050128HKG-001R2

## Equipment Photographs

Model : 72600A

(Internal)



# INTERTEK TESTING SERVICE

---

Report: 14050128HKG-001R2

## Equipment Photographs

**Model : 72600A**

**(Internal)**

