

APPENDIX B Tel: +886 2 26099301 Fax: +886 2 26099303

# APPDNDIX B

## **TEST PHOTOGRAPHS**

(Model: FXE3000-US)

File Number: C1M1603182Report Number: EM-EM-F160206This test report may be reproduced in full only. The document may only be updated by AUDIX Technology<br/>Corp. personnel. Any changes will be noted in the Document History section of the report.



### **B.1** Radiated Measurement at Fully Semi-Anechoic Chamber

Antenna #1: ACM3-5036-A1-CC-S (Integrated Antenna)



Antenna #2: ACM3-5036-A1-CC-S (FX-ANT-A8)



File Number: C1M1603182

Report Number: EM-EM-F160206

This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.




AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan APPENDIX B-Page 2 of 3 Tel: +886 2 26099301

Fax: +886 2 26099303

#### Antenna #3: ANTDP-048A



Antenna #4: MR-1700-W



File Number: C1M1603182


Report Number: EM-EM-F160206

This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX B-Page 3 of 3 Tel: +886 2 26099301 Fax: +886 2 26099303

#### **B.2 RF Conducted Measurement**



File Number: C1M1603182Report Number: EM-EM-F160206This test report may be reproduced in full only. The document may only be updated by AUDIX Technology<br/>Corp. personnel. Any changes will be noted in the Document History section of the report.