



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 19, 2001

RE: Interpoch Technology Inc.

FCC ID: PRL-IWE1200

I have a few comments on this Application.

- 1.) The manual lacks required prohibitions for co-location of this transmitter with any other transmitter or antenna
- 2.) Please indicate where the RF section is located on the Schematic.
- 3.) Please indicate where the RF section is located on the Block Diagram.

Thank you

William H. Graff
President and Examining Engineer

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.