



Product Service

Thursday, 06 June 2013

Attn: Federal Communication Commission

445 12<sup>th</sup> Street SW, Washington, DC 20554

U.S.A.

**TÜV SÜD BABT** 

Octagon House, Concorde Way, Segensworth North, Fareham, Hampshire, PO15 5RL, United Kingdom Telephone: +44(0)1489 558100 Fax: +44(0)1489 558101

Direct Dial: +44 (0)1489 558183 E-mail: NEmery@tuvps.co.uk Website: <u>www.babt.com</u>

Dear Sir / Madam,

We, TUV SUD BABT hereby request in pursuant to Section 2.917(a) of the rules of the code of Federal Regulation for dismissal for the device FCC ID: PROA100WI.

The request for dismissal is due to the grant was issued with the incorrect Grantee code 'PRO'. The grantee is Topview Optronics Corp. whose grantee code is RPO.

We can confirm that the device was not sold or marketed and will not be sold or marketed anywhere with an FCC ID of PROA100WI

Yours sincerely

Nathan Emery

**BABT Senior Certification Engineer** 

NJE/BABT 2013 Page 1 of 1