

Dear Mr. Dayhoff,

In response to your correspondence (Your Reference No. 24680) please find attached a revised version of the equipment ID label. As you may be aware, this application is essentially a resubmission of a previous application in response to changes in FCC regulations.

There appears to be some confusion regarding Exhibit 8. According to my files this should apply to the Technical Report for 'Technical Report, Type Approval Procedures and Test Report for the SSMS Transceiver Model CT2A', Release 1.3, December 20, 2002. This report has been revised and is in the FCC database.

The user manual (Release 1, 2001 June 12 ) does not require revision at this time and can be considered as current.

Best Regards,

Chris Rampen  
BotCorp America