



TRP Inc.

November 23, 2005

Federal Communications Commission, Laboratory
Oakland Mills RD
Columbia, MD 21046

Gentlemen:

Submitted herewith is a request for a new certification for Philips FCC ID:PT5TSU3500. This request is pursuant to changes in the layout of the RF output circuit of a previously certified device. If you have any questions, please call Phillip Inglis at 410 531 3439 or contact via email at jinglis@erols.com.

Sincerely,

Phillip Inglis
Consultant

