

Wistron Corporation

21F., No. 88, Sec. 1, HsinTai 5th Rd., Hsichih Dist, New Taipei City 221, Taiwan

Tel: +886-2-66121641 ; Fax: +886-2-66122188

To whom it may concern:

This device with FCC ID: PU5-TP00076BUC/ IC: 4182A-TP00076BUC integrates a WWAN module:

	Brand	FCC ID	IC ID
WWAN module	Sierra Wireless	N7NEM7455	2417C-EM7455

No hardware design changes are made on the modules, and the software has not been changed to increase the RF output power of the modules. Pursuant to KDB 996369 D01v02, the original modular report (Report Number:B15W50341-FCC-RF_Rev2) is submitted to represent the compliance of Part 22H/24E/27/90/ RSS-130/RSS-132/ RSS-133/ RSS-139/RSS-199 conducted testing items of this device. Radiated testing items are performed on the host level to ensure the compliance is kept.

Should you have any comments or questions, please feel free to contact me.

Sincerely,



Eric Shu

eric_shu@wistron.com