Wistron Corporation

21F., No. 88, Sec. 1, HsinTai 5th Rd., Hsichih Dist, New Taipei City 221, Taiwan Tel: +886-2-66121641; Fax: +886-2-66122188

To whom it may concern:

This device with FCC ID: PU5-TP00076BUC/ IC: 4182A-TP00076BUC integrates a Wi-Fi/BT module:

	Brand	FCC ID	IC ID
Wi-Fi/BT module	Intel	PD98260NG	1000M-8260NG

No hardware design changes are made on the modules, and the software has not been changed to increase the RF output power of the modules. Pursuant to KDB 996369 D01v02, the original modular report (Report Number:

SAR.20151009/1540055R-RFUSP05V00-A/1540055R-RFUSP05V00/1540055R-RFUSP 01V00/1540055R-RFUSP01V00-A/1540055R-RFUSP01V00-B/1540055R-RFCAP05V00 -A/1540055R-RFCAP05V00/1540055R-RFCAP01V00/1540055R-RFCAP01V00-A/1540 055R-RFCAP01V00-B/1570011S-CUSTOM/1570011S-CUSTOM-A) are submitted to represent the compliance of Part 2/15C/15E /RSS-102/RSS-247 testing items of this device.

Should you have any comments or questions, please feel free to contact me.

Sincerely,

Eric Shu

eric_shu@wistron.com

Evic Shu