

**Wistron Corporation**

21F, 88, Sec.1, Hsin Tai Wu Rd.,  
Hsichih, Taipei Hsien 221, Taiwan, R.O.C.  
Telephone: 886-2-6616-9999  
Facsimile: 886-2-6612-2188

## Justification of Supersession

Date: April 1, 2019

TO: Federal Communication Commission  
Equipment Authorization Branch  
7435 Oakland Mills Road  
Columbia, MID 21046

To whom it may concern:

This justification is for a purpose of requesting for permissions of putting the filing of authorized equipment:

FCC ID: PU5BT3, Grant Date: 03/27/2017

into auditor mode to allow the granting TCB to supersede the exhibitions of test report that has already been publicized on FCC host site with correct version.

Due to incorrect test data which applicable to §15.207 was misplaced in the EMC test report(s), we plead the replacement of the existing EMC test reports with revised ones that contain the correct test data.

There is no modification occurred to the authorized equipment, hence this request is ensured not applicable to any provisions related to changes in certificated equipment such as §2.1043.

In order to reflect the authenticity of every detail compliance, we deem the supersession of test report that entails falsified measurement result is necessary.

File name of the Test Report:

( File Name: Test Report-MPE and Report Number: ER/2017/30030, ER/2017/30031 )


File number of the new Test Report:

( File Name: ER-2017-30030-01 P15.247 BT+EDR, ER-2017-30031-01 P15.247 BLE and Report Number: ER/2017/30030-01, ER/2017/30031-01 )

Exhibition Type:

Test Report

Best regards,



Signature:

Name (Printed): Roy Hsieh

Title: RF Regulatory Director

On behalf of Company: Wistron Corporation

Telephone: 886-2-8691987

Address: 21F, 88, Sec. 1, Hsin Tai Wu Rd., Hsichih, Taipei Hsien 221, Taiwan