




2004 10 21



2004 10 21



2004 10 21



3004 10 31



RF 1

IOA

RF 2

IOA

RF 3

OA

RBS 3

OA

RBS 2

OA

RBS 1

OA

CSU

A

CTRL 1

A

CTRL 2

EAS

BIC

AIC

AUX





Rx DIV. TEST



Rx TEST



Tx TEST




POWER

ALARM

Tx ATTENUATION





RX IN

T
TE
PO

TX
OUT

RX IN

RX

OUT

DIV IN

LNA IN

Tx TEST

ALARM

POWER

Tx OMNI

Rx OMNI

DIV OMNI

A

B

C

A

B

C

A

B

C

FAN 1 FAN 2



2004 10 21