Fire Systems Group

Honeywell International 12 Clintonville Road Northford, CT 06472

203-484-6405 203-484-7118 Fax

Contact nameJonathan PotterDesignationGlobal Regulatory Director - HBTE-Mail ID:jonathan.potter@honeywell.com

To: Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

and

Innovation, Science and Economic Development Canada Certification and Engineering Bureau P.O. Box 11490, Station H 3701 Carling Avenue (Building 94) Ottawa, Ontario K2H 8S2

Subject: C2PC Request letter

Honeywell International Inc hereby requests a Permissive change Class II for CLSS Gateway

- 1) FCC ID: <u>PV3CGWMB</u> granted on 02/14/2020
- 2) IC ID: <u>1609A- CGWMB</u> granted on 05/12/2020

Modifications: -

- 1) Changes in USB connector, Inner Isolation of GND and shell.
- 2) SOM Module Change:
- a. Supervisor solutions from MAX6320PUK29DY+T(U12) to MAX16002DTC+T(U11)
- 3) Removed Parts: U12, U9, R120, C179, C1.
- 4) Added Parts: U11, C82, R43, R44, R127, C184, R129, R126, R128, C181, C182, R21
- 5) Product name has been changed from GLSS gateway to CLSS Gateway and Module Identification from CGW-MB to HON-CGW-MBB without any Technical changes
- CLSS gateway contains approved cellular Module (FCC ID: RI7LE910NAV2, IC: 5131A-LE910NAV2 OR FCC ID: RI7LE910SVV2, IC: 5131A-LE910SVV2)
- 7) HVIN Number is changed to HON-CGW-MBB

Sincerely,

Jonathan Potter Global Regulatory Director – Honeywell Building Technologies Honeywell International, Inc 12 Clintonville Road Northford, CT 06472