



Annex B of test report R80660_A
EUT: cB-0905-02-01
Manufacturer: connectBlue AB



80660_a.jpg

cB-0905-02-01 sample "24", top view


Annex B of test report R80660_A
EUT: cB-0905-02-01
Manufacturer: connectBlue AB



80660_b.jpg

cB-0905-02-01 sample "24", shielding removed, top view


Annex B of test report R80660_A
EUT: cB-0905-02-01
Manufacturer: connectBlue AB



80660_c.jpg

cB-0905-02-01 bottom view


Annex B of test report R80660_A
EUT: cB-0905-02-01
Manufacturer: connectBlue AB



80660_d.jpg

cB-0903-02-01 carrier board, top view

Annex B of test report R80660_A
EUT: cB-0905-02-01
Manufacturer: connectBlue AB



80660_e.jpg

cB-0903-03 carrier board, bottom view

Annex B of test report R80660_A
EUT: cB-0905-02-01
Manufacturer: connectBlue AB



80660_f.jpg

R380.500.139 antenna