

30th January 2004

Mr. N. Cobb
Radio Frequency Investigation Ltd.
Ewhurst Park
Ramsdell
Basingstoke
Hampshire
RG26 5RQ

Dear Mr. Cobb,

Re: Transfer of products from FCC Grantee Code MAY to PW9

In relation to our application for change of FCC identifier of our mass movement sensor products, I can confirm the change of identifiers as follows: -

Old FCC Identifier	Date of original grant	New FCC Identifier
MAYDA5815	09/27/1995	PW9DA5815
MAYDA5823	08/23/2002	PW9DA5823
MAYDA58233	04/29/2003	PW9DA58233

In respect of the above changes I can confirm that: -

1. The products will be manufactured from exactly the same drawings and printed circuit layouts as previously.
2. The products with the new identifiers do not differ in any respect from the original design.
3. The original test results continue to be representative of and applicable to the equipment bearing the new identifier.

I believe that this satisfies the requirements of 47 CFR 2.933.

Yours sincerely,



Neil R. Barker C.Eng. MIEE MIEEE MSEE
Manager
Compliance Engineering