

16<sup>th</sup> July 2004

Radio Frequency Investigation Ltd  
Ewhurst Park  
Ramsdell  
Basingstoke  
Hampshire  
RG26 5RQ

Dear Sir / Madam

FCC submission PW9DA58233

Tuning of the DA58233 series is performed during manufacture by laser trimming of tuning components. Adjustments cannot be made during the normal life of the equipment.

Yours Faithfully



Samantha Ridler BEng MIEE  
Compliance Engineer