

December 12, 2023

## Attestation For Wilson Signal Booster: FCC ID PWO075

FEDERAL COMMUNICATIONS COMMISSION Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

RE: Attestation for FCC ID: PWO075

To Whom It May Concern:

Each Signal Booster certificated under FCC ID PWO075 is manufactured and individually tested to ensure FCC compliance:

- (1) Licensee consent is not required for FCC certification equipment authorization purposes, but licensee consent does remain applicable per 20.21 provisions for both provider specific and wideband boosters.
- (2) NPS and other compliance/safeguard features have been implemented.
- (3) NPS and other compliance/safeguard features are defaulted to be "On" (in operation).
- (4) NPS and other compliance/safeguard features cannot be field reconfigured, disabled, or removed.
- (5) This consumer booster is not user programmable, does not need fine tuning or adjustment, and does not require professional installation.
- (6) Future software upgrade will not cause non-compliance.

Sincerely,

Ilesh Patel Senior Engineering Product Manager