

3301 East Deseret Drive St. George, Utah 84790 www.wilsonelectronics.com info@wilsonelectronics.com

Phone 800.204.4104 • Fax 435.656.2432

May 15, 2012

## Tuning and Adjustment of Wilson Model 2B5125 Signal Booster

There are no external tuning or other adjustments.

Sincerely,

Richard M. Kline

Senior Electrical Engineer