




# **Annex H**


## **Occupied Bandwidth**



### CDMA\_Downlink Input\_1960 MHz




### CDMA\_Downlink Input\_2132.5 MHz






### CDMA\_Downlink Input\_737 MHz




### CDMA\_Downlink Input\_751.5 MHz






### CDMA\_Downlink Input\_881.5 MHz




### CDMA\_Downlink Output\_1960 MHz






### CDMA\_Downlink Output\_2132.5 MHz




### CDMA\_Downlink Output\_737 MHz






### CDMA\_Downlink Output\_751.5 MHz




### CDMA\_Downlink Output\_881.5 MHz






### CDMA\_Uplink Input\_1732.5 MHz




### CDMA\_Uplink Input\_1880 MHz






### CDMA\_Uplink Input\_707 MHz




### CDMA\_Uplink Input\_781.5 MHz








### CDMA\_Uplink Input\_836.5 MHz




### CDMA\_Uplink Output\_1732.5 MHz






### CDMA\_Uplink Output\_1880 MHz




### CDMA\_Uplink Output\_707 MHz






### CDMA\_Uplink Output\_781.5 MHz




### CDMA\_Uplink Output\_836.5 MHz






### GSM\_Downlink Input\_1960 MHz




### GSM\_Downlink Input\_2132.5 MHz






### GSM\_Downlink Input\_737 MHz




### GSM\_Downlink Input\_751.5 MHz






### GSM\_Downlink Input\_881.5 MHz




### GSM\_Downlink Output\_1960 MHz






### GSM\_Downlink Output\_2132.5 MHz




### GSM\_Downlink Output\_737 MHz






### GSM\_Downlink Output\_751.5 MHz




### GSM\_Downlink Output\_881.5 MHz








### GSM\_Uplink Input\_1732.5 MHz




### GSM\_Uplink Input\_1880 MHz






### GSM\_Uplink Input\_707 MHz




### GSM\_Uplink Input\_781.5 MHz






### GSM\_Uplink Input\_836.5 MHz




### GSM\_Uplink Output\_1732.5 MHz






### GSM\_Uplink Output\_1880 MHz




### GSM\_Uplink Output\_707 MHz






### GSM\_Uplink Output\_781.5 MHz




### GSM\_Uplink Output\_836.5 MHz






### WCDMA\_Downlink Input\_1960 MHz




### WCDMA\_Downlink Input\_2132.5 MHz






### WCDMA\_Downlink Input\_737 MHz




### WCDMA\_Downlink Input\_751.5 MHz






### WCDMA\_Downlink Input\_881.5 MHz




### WCDMA\_Downlink Output\_1960 MHz








### WCDMA\_Downlink Output\_2132.5 MHz




### WCDMA\_Downlink Output\_737 MHz






### WCDMA\_Downlink Output\_751.5 MHz




### WCDMA\_Downlink Output\_881.5 MHz






### WCDMA\_Uplink Input\_1732.5 MHz




### WCDMA\_Uplink Input\_1880 MHz






### WCDMA\_Uplink Input\_707 MHz




### WCDMA\_Uplink Input\_781.5 MHz






### WCDMA\_Uplink Input\_836.5 MHz




### WCDMA\_Uplink Output\_1732.5 MHz






### WCDMA\_Uplink Output\_1880 MHz




### WCDMA\_Uplink Output\_707 MHz





### WCDMA\_Uplink Output\_781.5 MHz



### WCDMA\_Uplink Output\_836.5 MHz

