




Annex D


Conducted Spurious Emissions



Downlink_1930 - 1995 MHz_lower_100 ft cable




Downlink_1930 - 1995 MHz_upper_100 ft cable






Downlink_2110 - 2155 MHz_lower_100 ft cable




Downlink_2110 - 2155 MHz_upper_100 ft cable






Downlink_728 - 746 MHz_lower_100 ft cable




Downlink_728 - 746 MHz_upper_100 ft cable






Downlink_746 - 757 MHz_1559 - 1610 MHz_NB_100 ft cable




Downlink_746 - 757 MHz_1559 - 1610 MHz_WB_100 ft cable






Downlink_746 - 757 MHz_lower_100 ft cable




Downlink_746 - 757 MHz_upper_100 ft cable






Downlink_776 - 787 MHz_763 - 775 MHz_100 ft cable




Downlink_776 - 787 MHz_793 - 805 MHz_100 ft cable






Downlink_869 - 894 MHz_lower_100 ft cable




Downlink_869 - 894 MHz_upper_100 ft cable






Uplink_1710 - 1755 MHz_lower_100 ft cable




Uplink_1710 - 1755 MHz_upper_100 ft cable






Uplink_1850 - 1915 MHz_lower_100 ft cable




Uplink_1850 - 1915 MHz_upper_100 ft cable






Uplink_698 - 716 MHz_lower_100 ft cable




Uplink_698 - 716 MHz_upper_100 ft cable






Uplink_776 - 787 MHz_1559 - 1610 MHz_NB_100 ft cable




Uplink_776 - 787 MHz_1559 - 1610 MHz_WB_100 ft cable






Uplink_776 - 787 MHz_763 - 775 MHz_100 ft cable




Uplink_776 - 787 MHz_793 - 805 MHz_100 ft cable






Uplink_776 - 787 MHz_lower_100 ft cable




Uplink_776 - 787 MHz_upper_100 ft cable






Uplink_824 - 849 MHz_lower_100 ft cable




Uplink_824 - 849 Hz_upper_100 ft cable






Downlink_1930 - 1995 MHz_lower_300 ft cable




Downlink_1930 - 1995 MHz_upper_300 ft cable






Downlink_2110 - 2155 MHz_lower_300 ft cable




Downlink_2110 - 2155 MHz_upper_300 ft cable






Downlink_728 - 746 MHz_lower_300 ft cable




Downlink_728 - 746 MHz_upper_300 ft cable






Downlink_746 - 757 MHz_1559 - 1610 MHz_NB_300 ft cable




Downlink_746 - 757 MHz_1559 - 1610 MHz_WB_300 ft cable






Downlink_746 - 757 MHz_763 - 775 MHz_300 ft cable




Downlink_746 - 757 MHz_793 - 805 MHz_300 ft cable






Downlink_746 - 757 MHz_lower_300 ft cable




Downlink_746 - 757 MHz_upper_300 ft cable






Downlink_869 - 894 MHz_lower_300 ft cable




Downlink_869 - 894 MHz_upper_300 ft cable






Uplink_1710 - 1755 MHz_lower_300 ft cable




Uplink_1710 - 1755 MHz_upper_300 ft cable






Uplink_1850 - 1915 MHz_lower_300 ft cable




Uplink_1850 - 1915 MHz_upper_300 ft cable






Uplink_698 - 716 MHz_lower_300 ft cable




Uplink_698 - 716 MHz_upper_300 ft cable






Uplink_776 - 787 MHz_1559 - 1610 MHz_NB_300 ft cable




Uplink_776 - 787 MHz_1559 - 1610 MHz_WB_300 ft cable






Uplink_776 - 787 MHz_763 - 775 MHz_300 ft cable




Uplink_776 - 787 MHz_793 - 805 MHz_300 ft cable






Uplink_776 - 787 MHz_lower_300 ft cable




Uplink_776 - 787 MHz_upper_300 ft cable






Uplink_824 - 849 MHz_lower_300 ft cable




Uplink_824 - 849 MHz_upper_300 ft cable






Cond Spur_DL_1930 - 1990 MHz_lower_p1710013_200 ft




Cond Spur_DL_2110 - 2155 MHz_lower_p1710013_200 ft






Cond Spur_DL_728 - 746 MHz_lower_p1710013_200 ft




Cond Spur_DL_728 - 746 MHz_upper_p1710013_200 ft






Cond Spur_DL_746 - 757 MHz_1559 - 1610 MHz_NB_p1750018_200 ft




Cond Spur_DL_746 - 757 MHz_1559 - 1610 MHz_WB_p1750018_200 ft






Cond Spur_DL_746 - 757 MHz_763 - 775 MHz_p1750018_200 ft




Cond Spur_DL_746 - 757 MHz_793 - 805 MHz_p1750018_200 ft






Cond Spur_DL_746 - 757 MHz_lower_p1710013_200 ft




Cond Spur_DL_746 - 757 MHz_upper_p1710013_200 ft






Cond Spur_DL_869 - 894 MHz_lower_p1710013_200 ft




Cond Spur_DL_869 - 894 MHz_upper_p1710013_200 ft






Cond Spur_UL_1710 - 1755 MHz_lower_p1710013_200 ft




Cond Spur_UL_1850 - 1910 MHz_lower_p1710013_200 ft






Cond Spur_UL_698 - 716 MHz_lower_p1710013_200 ft




Cond Spur_UL_698 - 716 MHz_upper_p1710013_200 ft






Cond Spur_UL_776 - 787 MHz_1559 - 1610_NB_MHz_p1750018_200 ft




Cond Spur_UL_776 - 787 MHz_1559 - 1610_WB_MHz_p1750018_200 ft






Cond Spur_UL_776 - 787 MHz_763 - 775 MHz_p1750018_200 ft




Cond Spur_UL_776 - 787 MHz_793 - 805 MHz_p1750018_200 ft






Cond Spur_UL_776 - 787 MHz_lower_p1710013_200 ft




Cond Spur_UL_776 - 787 MHz_upper_p1710013_200 ft





Cond Spur_UL_824 - 849 MHz_lower_p1710013_200 ft



Cond Spur_UL_824 - 849 MHz_upper_p1710013_200 ft

