




Annex I


Oscillation Detection



Detection Time_Uplink_1710 - 1755 MHz




Detection Time_Uplink_1850 - 1910 MHz






Detection Time_Uplink_698 - 716 MHz




Detection Time_Uplink_776 - 787 MHz






Detection Time_Uplink_824 - 849 MHz




Detection Time_Downlink_1930 - 1990 MHz






Detection Time_Downlink_2110 - 2155 MHz




Detection Time_Downlink_728 - 746 MHz






Detection Time_Downlink_746 - 757 MHz




Detection Time_Downlink_869 - 894 MHz






Restart time_Uplink_1710 - 1755 MHz




Restart time_Uplink_1850 - 1910 MHz






Restart time_Uplink_698 - 716 MHz




Restart time_Uplink_776 - 787 MHz






Restart time_Uplink_824 - 849 MHz




Restart time_Downlink_1930 - 1995 MHz






Restart time_Downlink_2110 - 2155 MHz




Restart time_Downlink_728 - 746 MHz





Restart time_Downlink_746 - 757 MHz



Restart time_Downlink_869 - 894 MHz

