


Annex F

Uplink Inactivity

Uplink Inactivity_B12 UL_698 - 716 MHz_p2040010



Uplink Inactivity_B13 UL_776 - 787 MHz_p2040010

