Compliance Statement Pursuant to CC Docket No. 94-102, Section 22.921

Sony Ericsson Mobile Communications Inc certifies that it is in full compliance with Section 22.921 of the FCC's Rules. Sony Ericsson Mobile Communications has received approval for its call processing method and has incorporated required modifications rendering it fully compliant with 47 C.F.R. Section 22.921 of the FCC's Rules. (See DA 00-253 released February 11, 2000)

Conrad Geibel Project Manager As per 22.919, Electronic Seal Numbers

Protection Against Unauthorized ESN and Firmware Upgrades

The Electronic Serial Number (ESN) bits in this phone are encoded and spread over various non-sequential memory locations in order to prevent detection and modification. Once the factory has programmed the ESN, the mobile firmware cannot overwrite or alter the ESN memory locations. Both the ESN host and operation systems components are permanently mounted to the mobile in order to prevent removal and misuse. Unauthorized attempts to alter the mobile's firmware will cause the unit to become inoperable.

Conrad Geibel / Project Manager