

## 順風(私人)有限公司 ZEPHYR COMPANY (PTE) LTD

19 Woodlands Terrace, Singapore 738444

Tel: 6755 3922 Fax: 6755 3911

		K007/03
то	1	
ATTN	:	
FAX	:	
FROM	:	
QUOTE F	ŒF:	

Part No. = LAB-1014-00

APRT-2518	s G Rou	tei
MAC	D:	
S/N	lo:	
TC ;	tules. Operation is we conditions: (1) to armful interference	s with Part 15 of the FCC subject to the following his device may not cause, and (2) this device mus ence received, including
CEM	nterference that peration.	
FCC ID: PXI	2000003	MADE IN CHINA

Wireless G Ro	uter
MAC ID:	
S/No:	
Rules. Operation two conditions: (final interference accept any interference)	lies with Part 15 of the FCC is subject to the following I) this device may not cause ice, and (2) this device must ference received, including it may cause undesired
FCC ID: PXP000003	MADE IN CHINA

200%

Please note: Print specifications of finished part may deviate up to 10% due to inherent press tolerances

FILENAME: R18068-G ROUTER-RD		FILM:		REQUESTED BY: VN/JL	CUSTOMER APPROVAL / DATE:
SIZE 39X59 MM	COLOUR:	DATE: 24-10-2005	CREATED BY: YT*C2	VERIFIED BY :	Xm 27/10/05