

April 25, 2005

RE: Netgear Inc.

FCC ID: PY3GR613VAL

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) The required information to the user information of 15.21 appears to be missing. Kindly review the Manual
- 2.) Please confirm if the copper tape and ferrites seen in the Internal Photographs will be used on all production products. Kindly supply photographs of the final electrical and mechanical fixes used on all production units.

Willing

William H. Graff President and Director of Engineering

mailto: whgraff@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.