
### Page 97 / 402 Report No.: TCWA23110002404




Sushi TOWE Wireless Testing(Shenzhen) Co., Ltd. Tel.: +86-755-27212361

Email: info@towewireless.com

TOWE-QP-15-F05 Rev.1.0

#### Page 98 / 402 Report No.: TCWA23110002404




Sushi TOWE Wireless Testing(Shenzhen) Co., Ltd. Tel.: +86-755-27212361

Email: info@towewireless.com

TOWE-QP-15-F05 Rev.1.0

#### Page 99 / 402 Report No.: TCWA23110002404




Sushi TOWE Wireless Testing(Shenzhen) Co., Ltd. Tel.: +86-755-27212361

Email: info@towewireless.com

TOWE-QP-15-F05 Rev.1.0

### Page 100 / 402 Report No.: TCWA23110002404




Sushi TOWE Wireless Testing(Shenzhen) Co., Ltd. Tel.: +86-755-27212361

Email: info@towewireless.com

TOWE-QP-15-F05 Rev.1.0

### Page 101 / 402 Report No.: TCWA23110002404




Sushi TOWE Wireless Testing(Shenzhen) Co., Ltd. Tel.: +86-755-27212361

Email: info@towewireless.com

TOWE-QP-15-F05 Rev.1.0

### Page 102 / 402 Report No.: TCWA23110002404




Sushi TOWE Wireless Testing(Shenzhen) Co., Ltd. Tel.: +86-755-27212361

Email: info@towewireless.com

TOWE-QP-15-F05 Rev.1.0

### Page 103 / 402 Report No.: TCWA23110002404




Sushi TOWE Wireless Testing(Shenzhen) Co., Ltd. Tel.: +86-755-27212361

Email: info@towewireless.com

TOWE-QP-15-F05 Rev.1.0

#### Page 104 / 402 Report No.: TCWA23110002404




Sushi TOWE Wireless Testing(Shenzhen) Co., Ltd. Tel.: +86-755-27212361

Email: info@towewireless.com

TOWE-QP-15-F05 Rev.1.0

### Page 105 / 402 Report No.: TCWA23110002404




Sushi TOWE Wireless Testing(Shenzhen) Co., Ltd. Tel.: +86-755-27212361

Email: info@towewireless.com

TOWE-QP-15-F05 Rev.1.0

#### Page 106 / 402 Report No.: TCWA23110002404



Sushi TOWE Wireless Testing(Shenzhen) Co., Ltd. Tel.: +86-755-27212361

Email: info@towewireless.com



### Test Graphs Straddle Channel





#### Page 108 / 402 Report No.: TCWA23110002404

