

Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 60 (74)

#### <u>Test setup</u>





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 61 (74)

#### Test site Radiated Emissions






Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 62 (74)

#### Test site Conducted emissions






Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 63 (74)

### Photographs of the equipment





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 64 (74)





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 65 (74)






Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 66 (74)





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 67 (74)





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 68 (74)





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 69 (74)





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 70 (74)





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 71 (74)





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 72 (74)





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 73 (74)





Test Report No.: 2\_3296-01-02/03

Issue Date: 2003-06-12

Page 74 (74)