

Confidential

1(1)

Prepared by  
SEMC/CVVALE Afrah Sadiq + 46 10 80 12250  
Contents responsible if other than preparer

Document number  
CVVA10:009  
Date  
2010-01-13  
Remarks

Revision  
A

Approved by  
SEMC/CVVALEC Peter Lindeborg + 46 10 80 16180

Receiver: Federal Communication Commission and  
Certification and Engineering Bureau  
Industry Canada


**Application: Type number: AAD-3880067-BV,**  
**FCC ID: PY7A3880067,**  
**Canada IC: 4170B-A3880067**

## Statement on Bluetooth hardware

Sony Ericsson mobile phone J10 (FCC ID: PY7A3880067, IC: 4170B-A3880067) uses the exact same Bluetooth hardware and software as J10i2 (FCC ID: PY7A3880065, IC: 4170B-A3880065).

Based on this, FCC part 15.247 and RSS – 210 Issue 7 report (report no. 1-1065-70-04/09, dated 2009-12-16) issued for J10i2 also applies for J10.

Best regards,



Peter Lindeborg

Technical Manager – EMF and Safety

Sony Ericsson Mobile Communications AB - Lund

Sony Ericsson Mobile Communications AB

Postadress • Mail  
SE-221 88 Lund  
Sweden

Besöksadress • Office address  
Nya Vattentornet  
Lund

Styrelsens säte: Lund  
Registered office: Lund  
Telefon • Telephone  
Nat 010-80 00000  
Int +46 10 80 00000

Momsnr • V.A.T.No: SE556615665801  
Organisationsnr • Reg No: 556615-6658  
Telefax • Telefax  
Nat 010-80 02040  
Int +46 10 80 02040