

Tuning Procedure

There are no tuning procedures. Manufacturing tolerances have been designed so that an accumulation of worst case component variation will not exceed the allowable output power of 3 watts.