

AeroScout[®]

Date: February 10, 2020

Attn: Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern:

The AeroScout, FCC ID: Q3HTAG1200S, and label are so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3)

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:


- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

Thank you,

Signature:
Reuven Amsalem
VP HW R&D

A handwritten signature in black ink, appearing to be 'Reuven Amsalem', written over the printed name and title.