



Date: 4/23/2023

To: Federal Communications Commission, 7435 Oakland Mills Road,  
Columbia, MD 21046, USA

Attn: Reviewing Engineer

To Whom It May Concern:

AeroScout's FCC ID: Q3HTAGB1200SB and label are so small, that it cannot include the statement specified in 47 CFR Part 15 Sub-part A, Section 15.19 (a) (3).

Under the provisions of 47 CFR Part 15 Sub-part A, Section 15.19 (a) (5), this statement appears in a prominent location in the user manual.

Thank you,

A handwritten signature in black ink, appearing to read "RA" with a stylized flourish.

Reuven Amsalem  
VP HW R&D