



February 18, 2009

ATTN: Reviewing Engineer

RE: Motion Computing X5 Series Tablet PC (Model: CFT-00x where "x" can be "1" or "2")

FCC ID: **Q3QHWMSMC5725**

IC ID: **4587A-SWMC5725**

To Whom It May Concern:

This letter has been generated to provide the reviewing Engineer the "Tune-up Procedures" related to the X5 Tablet PC (where "X" can be "C" or "F") Model CFT-00x (where "x" can be "1" or "2"). Please reference "Declaration of Identity" for explanation of model number naming convention.

Motion Computing "Q3QHWMSMC5725" module does not require nor is allowed to be tuned up other than what has been programmed by the manufacturer (Sierra Wireless) upon component shipment to Motion Computing or to any Motion Computing affiliates.

Sincerely,

A handwritten signature in black ink, appearing to read "Don Bobo", is written over a faint, larger version of the signature.

Don Bobo

Motion Computing Incorporated ®

8601 Ranch Road 2222

Building 2; Austin, TX 78730

512-637-1149 (Direct)

512-637-1199 (Fax)

DBobo@Motioncomputing.com