

Helen Zhao

Subject: FW: ??: FW: Averatec Inc., FCC ID: Q3Z3300, Assessment NO.: AN04T4416, Notice#1



E1200 Test Rpt
Revised 1221.pd...

-----Original Message-----

From: ting@ccsemc.com.tw [mailto:ting@ccsemc.com.tw] On Behalf Of application@ccsemc.com.tw
Sent: Monday, December 20, 2004 4:54 PM
To: Helen Zhao
Cc: Application (CCS TW) (E-mail); Lucy Tsai (E-mail)
Subject: ??: FW: Averatec Inc., FCC ID: Q3Z3300, Assessment NO.: AN04T4416, Notice#1

Hi Helen,

The revised test report as attached.
Please refer to it.
(See attached file: E1200 Test Rpt Revised 1221.pdf)
BR,
Ting

-----Original Message-----

From: Compliance Certification Services [mailto:hzhao@ccsemc.com]
Sent: Monday, December 20, 2004 2:40 PM
To: Helen Zhao
Subject: Averatec Inc., FCC ID: Q3Z3300, Assessment NO.: AN04T4416, Notice#1

Question #1: The MPE calculation is incorrect. Please revise the test report.

Best Regards,
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an

identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.