## **Glen Ellen Laboratories**

1876 London Ranch Road Glen Ellen, CA 95442



(707) 996-8533

e-mail dan@glenellenlabs.com

(707) 996-2803 fax

FCC OET

re. Application for FCC ID Q4LWT0003

GEL Report File HP01-2003, dated April 26, 2003

for:

WeatherTRAK irrigation controller

made by

HydroPoint Data Systems inc. 1726 Corporate Circle Petaluma, CA 94954

I confirm that the modification made to the WeatherTRAK irrigation controller, the addition of copper tape over the two metal shields on the input sections of the receiver, as described on the test report, will be implemented on all production units.

Daniel C. Swann

President, Glen Ellen Laboratories

David C. Swan