



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 18, 2007

RE: FCC ID: Q5EPT720001_ATCB005184
Attention: Peter

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please provide a more detailed explanation of the "Wired Cloning Mode" function of the device. What is the intent of the cloning mode and how is this mode prevented from allowing a US transmitter from cloning the frequency setup for an EU transmitter. How is the user prevented from cloning non-US frequencies?

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.