

# WatchGuard Technologies, Inc.

505 Fifth Avenue South, Suite 500, Seattle, Washington, 98104, United States

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Date: 2022-07-28

Reference: FCC ID: **Q6G-AP332CR**

To The Commission:

This Change of Identification request applies for a new FCC ID: **Q6G-AP332CR** as established in 47CFR 2.933(b) for a currently approved device. This application by **WatchGuard Technologies, Inc.** will establish a new FCC ID under **Q6G** grantee code for purpose of marketing. The original grant to **FCC ID: A8J-EWS850AP** will remain in effect.

An authorization letter by **EnGenius Technologies** is attached.  
Per 2.933(b)

1. The original identification is FCC ID: **A8J-EWS850AP**
2. The original grant date is **08/13/2020**.
3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

**Cover Letter**

**External Photos**

**FCC ID label format and location**

Sincerely yours,



-----  
Jay Lindenauer, Vice President of Product Delivery Operations

**WatchGuard Technologies, Inc.**

Tel: 2068768103

Fax: 2065211400

# WatchGuard Technologies, Inc.

505 Fifth Avenue South, Suite 500, Seattle, Washington, 98104, United States

E-mail: [jay.lindenauer@watchguard.com](mailto:jay.lindenauer@watchguard.com)