## **Lucy Tsai**

From: aven.zhou [aven.zhou@cn.ccsemc.com]
Sent: Monday, May 26, 2008 1:43 AM

To: Lucy Tsai

Subject: Re:FW: Chung Nam Electronics Co., Ltd., FCC ID: Q72WLC100GA, Assessment NO.:

AN08T7880, Notice#2

Attachments: Q72WLC100GA-Block Diagram.pdf; Q72WLC100GA-OEM Manual.pdf; SZ080324B06-RP\_

0521.pdf; Setup Photo 0526.pdf

Dear Lucy,

Please kindly find the reply below in blue.

If there is any question, please contact me without hesitation!

Thanks & Best regards!

Aven.zhou (Miss) / 周 中 平

Compliance Certification Service(Shenzhen) Inc.

Tel: 0755-28055000 ext. 601 E-mail:aven.zhou@cn.ccsemc.com

tillyping@gmail.com

MSN : tilly\_ping@hotmail.com

Skype: aven\_zzp

"Lucy Tsai"

<a href="mailto:ucv.tsai@ccsemc.com">uv件人: "aven.zhou"<a href="mailto:aven.zhou@cn.ccsemc.com">aven.zhou@cn.ccsemc.com</a>

副本抄送:

2008-05-22 02:00 主旨: FW: Chung Nam Electronics Co., Ltd., FCC ID: Q72WLC100GA, Assessment NO.: ANO8T7880,

Notice#2

Hi Aven,

Please address following issues.

Q#1: Please provide a block diagram which has included all applicable oscillators in the device per Part 2.1033.

<Aven>The attached is the revised block diagram.

Q#2: As indicated in the user manual, 14 channels are available for this mini-PCI card which is not allowed. Also, the typical output power indicated in the user manual is 21 mW which is about 20 mW different from the measured result. Please address.

<Aven>The attached is the revised user manual.

Q#3: As indicated in section 2.6 of user manual, user is allowed to install this mini-PCI card which doesn't agree with modular approval. Noted that this device can only be installation by OEM integrators.

## <Aven> Section 2.6 was deleted from the user manual.

Q#4: As indicated in the test report, 3 planes of x, y, z axes were verified during the test. Please show out how the y and z axes were investigated.

<Aven>Please kindly find the revised report(P7)

Best Regards,

Lucy Tsai CCS

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.