

Chris Harvey

From: rick@etc.org.tw
Sent: Friday, January 16, 2004 7:52 PM
To: Chris Harvey
Subject: Re: Additional Information needed #AN03T3542 FCC ID: Q77WTVB



Report(9210058-03 connector.doc (2 ID Label.pdf (5 MB)
) .pdf (15 KB)...

Hi Chris,

Regarding this project, it is a TV interface device, we have made a test report for FCC DOC, it's including TV interface and 433MHz receiver (please refer to the attached file).

Attached please find the photograph of antenna connector, it is not a standard SMA connector, please reconfirm.

Label location please refer to the attached file, thanks!

Best regards,
Rick Hu

----- Original Message -----

From: "Chris Harvey" <charvey-tcb@CCSEMC.com>
To: <rick@etc.org.tw>
Cc: "Chris Harvey" <charvey-tcb@CCSEMC.com>
Sent: Monday, January 12, 2004 11:48 AM
Subject: FW: Additional Information needed #AN03T3542 FCC ID: Q77WTVB

> Rick,
>
> I have been reviewing the above referenced application for Beyond
Broadband
> Networks, Inc, and found the following issues with the application:
>
> This device appears to have a TV Tuner for CATV reception included on
> the main PC board. If this is a Cable Ready Consumer Electronics
> device, it requires compliance with FCC Rule Part 15.118 and
> associated rule parts. There was no documentation submitted showing
> compliance with these FCC requirements. Please submit this
> information.
>
> This device contains a 433MHz receiver (receives signals from RF
> Remote
> Control) however there does not appear to be any compliance information or
> technical information about the receiver in this device. Please provide
FCC
> compliance information about the 433 MHz receiver contained in this
device.
>
> According to the Users Manual, the 2.4GHz antenna connector is an SMA
> connector, which would violate the requirements of FCC 15.203 Antenna
> Requirements. Please submit documentation as to how this device will
comply

> with the requirements of FCC 15.203.
>
> There was no Label Location Diagram submitted as required by the FCC
Rules.
> Please submit a photograph or drawing showing the location of the FCC
> ID label.
>
> The items indicated above must be submitted before processing can
> continue on the above referenced application. Failure to provide the
> requested information within 30 days of the original e-mail date may
> result in application dismissal and forfeiture of the filing fee.
> Also, please note that partial responses increase processing time and
> should not be
submitted.
> Any questions about the content of this correspondence should be
> directed
to
> the e-mail address listed below the name of the sender.
>
> Please provide the above requested information to
> charvey-tcb@ccsemc.com
>
> Best regards,
>
> Chris Harvey
>
>