



Cisco-Linksys LLC

121 Theory Drive Irvine, CA 92617 (USA)

Phone: 949-261-1288 Fax: 949-823-3002

Date: October 30, 2007

Compliance Certification Services
Certification Division
561F Monterey Road
Morgan Hill, CA 95037

To whom it may concern:

We hereby declare that the device does not have Ad Hoc capabilities on non-US frequencies(5.25 ~ 5.35GHz & 5.470 ~ 5725 GHz) and on DFS frequencies and this device automatically discontinues operation of the transmitter in case of absence of information to transmit or in case of operational failure

Product: Wireless 802.11N DUAL BAND MINI PCI MODULE
Model: WM821-M-LS
FCC ID: Q87-WM821M

If you have any questions regarding this application, pls feel free to contact me.

Sincerely Yours,

A handwritten signature in black ink, appearing to read "Jennifer Yu".

Jennifer Yu / Program Manager
Cisco-Linksys LLC
TEL: +1 949-823-3188
FAX: +1 949-823-3002



E-Mail: jennyu@cisco.com

