



Cisco-Linksys LLC

121 Theory Drive Irvine, CA 92617 (USA)

Phone: 949-261-1288 Fax: 949-823-3002

Federal Communications Commission

7435 Oakland Mills Road

Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: SA3-AGN1223AR0300

To The Commission:

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by Linksys will establish a new FCC ID under Linksys's grantee code for purpose of marketing. The original grant to Airgo Networks Inc. will remain in effect.

An authorization letter by Airgo Networks Inc. is attached.

Per 2.933(b)

1. The original identification is SA3-AGN1223AR0300.
2. The original grant date is 01/04/2005.
3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely yours,

Jennifer Yu / Associate Engineer

Cisco-Linksys LLC

Tel.: (949) 823-3188

Fax: (949) 823-3002

jennyu@cisco.com