



Cisco-Linksys LLC
121 Theory Drive Irvine, CA 92617 (USA)
Phone: 949-261-1288 Fax: 949-823-3002

Federal Communications Commission
7435 Oakland Mills Road
Columbia MD 21046

Date: November 9, 2006
FCC ID: Q87-WRT350NV2

It is acknowledged by Cisco-Linksys LLC. that the modification list below will be installed to our Model: WRT350N Ver.2 in order to comply with FCC Rules. The following modifications will be incorporated into each unit sold under the rules.

#1. Added copper foil shielding on the PC board, please refer to EUT photos.

Best Regards

Sincerely yours,

A handwritten signature in black ink, appearing to read "Jennifer Yu".

Jennifer Yu / Product Engineer
November 9, 2006