



## *Cisco-Linksys LLC*

*121 Theory Drive Irvine, CA 92617 (USA)  
Phone: 949-261-1288 Fax: 949-823-3002*

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: Q87-WRT54GX2V2

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Airgo Networks will establish a new FCC ID under Cisco-Linksys LLC. grantee code for purpose of marketing. The original grant to Airgo Networks.  
FCC ID: SA3-AGN3012MP1100 will remain in effect.

An authorization letter by Airgo Networks. is attached.

Per 2.933(b)

1. The original identification is SA3-AGN3012MP1100
2. The original grant date is 05/15/2006.
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter  
External Photos  
FCC ID label format and location

Sincerely,

---

Jennifer Yu / Product Engineer  
August 7, 2006