



Cisco-Linksys LLC
121 Theory Drive Irvine, CA 92617 (USA)
Phone: 949-261-1288 Fax: 949-823-3002

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: [Q87-WRT54GX4](#)

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by [Airgo Networks, Inc.](#) will establish a new FCC ID under [Cisco-Linksys LLC](#) grantee code for purpose of marketing. The original grant to [Airgo Networks, Inc.](#)'s [FCC ID: SA3-AGN3023MX0100](#) will remain in effect.

An authorization letter by [Airgo Networks, Inc.](#) is attached.

Per 2.933(b)

1. The original identification is [SA3-AGN3023MX0100](#)
2. The original grant date is [10/24/2005](#)
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter
External Photos
FCC ID label format and location

Sincerely,

[Cisco-Linksys LLC](#)

Name: [Jennifer Yu](#)
Title: [Associate Engineer](#)
Date: [October 28, 2005](#)