

-US/EU

LINKSYS[®]
A Division of Cisco


CISCO

Simultaneous Dual-N Band Wireless Router




Model No. **WRT610N**




Serial No.:
[Redacted]

MAC Address:
[Redacted]




This device complies with part 15 FCC rules.
Operation is subject to the following two conditions:
(1) this device may not cause harmful interference
(2) this device must accept any interference received including interference that may cause undesired operations.
FCC ID: Q87-WRT610N IC:3839A-WRT610N
CANADA ICES/NMB003, RSS210 Class/Classe B

 I.T.E.  

Rating: 12V --- 1.5A
Web technical support for US & Canada : <http://www.linksys.com/support>
Made in China



-US/EU/AU

LINKSYS[®]
A Division of Cisco


CISCO

Simultaneous Dual-N Band Wireless Router




Model No. **WRT610N**




Serial No.:
[Redacted]

MAC Address:
[Redacted]




This device complies with part 15 FCC rules.
Operation is subject to the following two conditions:
(1) this device may not cause harmful interference
(2) this device must accept any interference received including interference that may cause undesired operations.
FCC ID: Q87-WRT610N IC:3839A-WRT610N
CANADA ICES/NMB003, RSS210 Class/Classe B

 I.T.E.  

Rating: 12V --- 1.5A
Web technical support for US & Canada : <http://www.linksys.com/support>
Made in China



WRT310N
Product label
Revision:C
04/10/2008

BLACK